



Technical drawing of a circular part with concentric circles. A dimension line with arrows indicates a radial distance from the center to the outer edge, labeled with the values 5,00, 0,00, and -0,10.



www.vetroricambi.it